



October 5, 1982

Mr. Allen W. Hinderacker Suite 4344 I.D.S. Tower Minneapolis, MN 55402

Dear Mr. Hinderacker:

I received another phone call from Mr. John Carun of E.R.T. on October 3. He had questions regarding the steps taken during the testing of Well 15 on September 15. He needed clarification of the size of the piping, the layout of the sand filters, as well as size, the length of piping runs, and when and where the chlorination and aeration were added, both pre-chlorination and post chlorination.

Sincerely,

Vern Tollefsrud

Water and Sewer Superintendent

jms